

Our Hard Copy Report



Nicely comb bound report with protected front and back covers

Easy to read and leaf through - see the online - downloadable version in the following pages



Prime Inspections Property Inspection Report



Sample Street, Nearby NY, 13833 Inspection prepared for: Jane Sample Agent: Jane Sample -

Inspection Date: 2/28/2009 Time: 11:00 AM Age: 75 years old Size: 2800 SQ Ft Weather: 65* F Nice and Sunny no rain within 24 hrs period

Inspector: Frank P. Macak License # 16000041526 2685 Patent Line rd., Franklin, NY, 13775 Phone: 607-829 2992 Fax: 607-829 2992

Email: primeinspections@citlink.net www.prime-inspect.com

"Inspecting is more than a skill, it is an art "

Ratings Definitions:

Good = Functional / in good working condition Fair = Functional / some maintenance needed Poor = Not performing to standards, will require repair or replacement N/A = Not applicable NI = Not inspected

Dear Mr. and Mrs. Sample,

I thank you for giving me the opportunity to evaluate this property. My inspection did not uncover any serious structural problems with the property.

There are however, some maintenance and/or repair issues that need to be addressed, to protect your investment. Issues requiring immediate maintenance or repair are included in the summary page at the end of the report, but you should carefully read through the entire report, as there are other small deficiencies and helpful maintenance issues discussed.

It is important to keep in mind the type of structure and/or the period it was built in, as building and safety standards do change with time. As inspectors, we point out the deficiencies in accordance with today standards, so that you can upgrade the systems according to the level of your comfort. We always advise our clients to upgrade the safety issues to modern standards to avoid any possible and unnecessary injury.

I would like to congratulate you on the purchase of your new home, and I hope that you enjoy it for many years to come.

Should you have any questions, please contact me any time.. Sincerely,

Frank P. Macak PRIME INSPECTIONS

Grounds

An evaluation of grounds area is very important, because most damage to a property is due to improper water drainage and water penetration into the structure. We look at the grading around the house, window wells, vegetation around the foundation, driveway and sidewalk conditions as well as the safety of porches and patios.

Recomendations: We recommend keeping all vegetation trimmed away at least 2 feet from the house. Vegetation too close to the house will cause abrasions to the siding or damage to the roof covering, but can also allow wood destroying insect to enter and cause damage to the structure. If not properly maintained, the driveways, walkways, decks, steps, patios and porches can present a trip hazard. Almost all houses have some sort of trip hazard present. Ground heaving during the winter can cause cracks in concrete or black top. Always seal the cracks as soon as possible with appropriate sealants as to prevent water entry that may cause more damage by the freeze and thaw cycle. The grading around the house should be ideally sloped 6" for 10 feet, away from the house. This will assure that the water is properly drained away from the structure. Gutter downspouts should have proper extensions directing the water away from the foundation. Another commonly found safety hazard is the porch and deck railings. Any steps/deck/porch/patio over 24" high should have a proper railing. Openings between the spindles should not allow a 4" diameter ball to pass through at any point, this is to assure that a childs head cannot get trapped between the spindles causing injury or even death.

1. Driveway and Walkway Condition



Materials: concrete. asphalt


Observations: small cracking in the surface of the asphalt driveway. Yearly application of the sealer will help to prevent any water damage by sealing the cracks is recommended

2. Patio and Porch Condition



Materials: sloped - shed type roof Observations: recommend removal of accumulated debris from the roof surface area

3. Patio and Porch Deck



Observations: concrete . exterior carpet

4. Stairs & Handrail



Observations: loose railing will need to be re tighten to prevent damage to the siding . loose step and missing spindle pose a safety and trip hazard. The missing spindle creates a condition where a child could get trapped and seriously injured. Immediate correction is needed.

5. Grounds Electrical



6. GFCI

Good	Fair	Poor	N/A
X			

Observations: test operated

7. Grading

Good Fair Poor N/A

NI

Observations: mostly flat. recommend grading the soil to divert the water away from the house. Allow at least 3" pitch for 5' of grade for proper drainage

Frank P. Macak

Page 2 of 33

8. Plumbing	
Good Fair Poor N/A NI	Materials: frost free faucet present. anti siphon device present
9. Water Pressure	
Good Fair Poor N/A NI	Observations: 110 lbs. While many people love the high pressure in the house, it might cause damage to the plumbing system. I would recommend 80 psi max.
10. Pressure Regul	lator
Good Fair Poor N/A NI	Observations: pressure is too high, recommend pressure regulator. Generally utility company will install free of charge
11. Gate Condition	
Good Fair Poor N/A NI X X X X X	Materials: wroght iron Observations: I'd recommend lubricating the hinges at least once a year for proper operation and corrosion prevention.

Exterior Areas

On the exterior of the house we look at the condition of the foundation, siding, eaves, fascia, rake and soffit materials and their condition. We also inspect gutters, window wells, windows, doors, electrical service entrance, the meter box and plumbing.

Recommendations: The exterior of the house also known as the "building envelope "is very critical to the whole structure. Its purpose is to keep the elements such as moisture, wind and temperature away from the interior of the structure. The building envelope is not water proof. Though it must not allow moisture in, it needs to allow the moisture trapped in the walls or attic to escape out. It is important that the roof, siding and foundation penetrations such as chimney, vent stack, conduit, cable TV, water, gas, fuel supply pipes entries, etc. to be properly flashed or sealed with appropriate sealand/caulk, to prevent water entry. The roof is designed to shed the water in the downward flow, so proper flashings of the valleys, sidewalls, chimneys and vent stacks are critical. Those need to be periodically inspected and maintained, especially if they were previously repaired - as roofing cement tends to dry up and develop cracks. Siding should be installed 6" above the ground to prevent absorption of the moisture from the ground or splashing. Keeping the siding away from the ground will also lessen the chance of entry by wood destroying organisms. Most type of sidings require proper maintenance in terms of painting, staining or pressure washing to keep it from damage by moisture, mold or mildew. Proper airflow around the structure helps keeping the structure dry and free of mildew and mold.

1. Fascia Condition Poor

Fair

Х

Good

N/A Materials: aluminum

Observations: poor workmanship in some areas, improperly cut, not sealed




poor workmanship in some areas, improperly cut, not sealed

2. Eaves & Facia Good Fair Poor N/A NI X I I
3. Cond. Good Fair Poor N/A NI X Image: N/A NI Materials: vented vinyl. boxed and vented
4. Gutters cond. Good Fair Poor N/A NI Materials: Aluminum Observations: sagging in the back part of the house. gutter extensions crushed, some missing
5. Siding Condition

Sample Street, Nearby, NY

Jane Sample



several corner moldings are not properly flashed at the top, allowing for water penetration behind the siding

rank P. Macak	Page 5 of 33	Prime Inspection
	Exterior Walls	
11. Foundation Good Fair Poor N/A NI X X X X X	Observations: concrete block with top coat finish. cer off in several places	ment top coating peeling
Good Fair Poor N/A NI X X X X	Observations: concrete block. stucco finish. Stucco of horizontal cracks. When making repairs, stucco shour removed to examine the mortar for cracks. I would resupport bracket or larger cricket behind the chimney, cracks.	ld be sufficiently commend installing a
9. Storm door con Good Fair Poor N/A NI X	nd. Materials: <i>aluminum</i>	
Source Source Good Fair Y V	Materials: 6 panel insulated fiberglass	
7. Condition Good Fair Poor N/A NI X I I I	Materials: wood double hung. aluminum clad Observations: paint peeling. trim clad with aluminum, around to prevent water penetration	needs to be caulked all
6. Exterior Paint	Observations: some areas have peeling, chipping pa the window trim and sash. Due to the age of the hous lead. If or when making repairs, treat it as such or ha professional do the work.	se, paint could contain

With the exterior walls, we look to see if they are plumb, if there are any bows or deflections, any rafter spread present and size of the structural members. In most cases it is impossible to asses the exterior walls insulation type and value, because we cannot do any deconstructive evaluation, that would cause damage to the finish surfaces. Current standards require a total of R-20 insulating value of the wall and 2x6 exterior wall construction.

Recommendations: To minimize the moisture entry from the interior of the house into exterior walls, it is a good idea to run exhaust fans whenever taking showers, range hood vents when cooking and making sure that dryer vents are properly vented to the exterior of the house. Checking and cleaning the dryer ductwork often is also recommended as it is known to separate. If there is moisture in the basement as is the case with many local area houses, consider adding dehumidifier or opening the basement windows in summer. Any penetrations of the envelope of the building should be properly sealed with an appropriate flexible sealant to prevent any possible water entry.

1. C	Cond	ditio	า		
Good	Fair	Poor	N/A	NI	
Х					Materials: 2x6 platform construction, Observations: unable to determine the insulation presence or value

Floors

The inspection of the floors involves visual observation of the type of materials used, method of installation and the current condition. Level, stiffness, deflections or buckling of the flooring surfaces is especially important to observe, as it could be an indicator of a larger, structural problems. Recommendations: Floor surfaces should be maintained according to manufacturers instructions. When moping the floors, use only a damp mop as any moisture trapped under the flooring can cause serious floor damage not only to the finish floor, but also to the underlayment or sub floor system. Prolonged exposure to moisture can cause a mold growth and rotting of the sub floors. The most susceptible areas to floor moisture damage are in the bathrooms around the tubs and toilets and by the entry doors due to failed door seals. Small soft/spongy areas in the floors most likely indicate sub floor damage.

1. Condition

N/A

NI

Good Fair Poor

Type: 2x8 construction Observations: open

Roof

The inspection of the roof involves, a visual observation from the ground with binoculars, from the ladder, or physically walking on the roof whenever possible. We try to assess the physical condition of the roof, its age, type of roofing material, installation method, soundness of the decking system, flashing condition and the approximate remaining life expectancy of the roof.

Recommendation: To get the maximum life out of the roof covering, it is important to keep roof surfaces clear of debris, such as dead branches or leaves/pine needles. Debris sitting on the roof will freeze to the shingles in the winter and tear the tabs of when it is pull down with the snow or ice or by the force of the wind. The same applies to live branches of trees that are touching the roof, which will also cause damage by abrasion when they are moved by wind. Sitting debris will also promote the growth of mildew, mold or lichen on the roofing surface and cause deterioration of the roofing materials as well as clogging of the gutter system and creating conditions conducive to water penetration. All flashings if previously repaired, should be inspected and repaired as necessary yearly. Walking on certain types of roof could void manufacturers warranty. Always have a qualified and licensed professional do the necessary maintenance and repairs, as walking on the roof is dangerous.

1. Roof Condition



Materials: gable/gable. with several dormers present Materials: asphalt shingles Observations: some cracked shingle. mildly deteriorated material in some areas. exposed nails

Page 6 of 33

Sample Street, Nearby, NY



	Remainig life span: 5-7 years with proper maintenance
4. Chimney	
Good Fair Poor N/A NI X I I I I	Observations: small cracks
5. Flashing	
Good Fair Poor N/A NI	Observations: aluminum step flashing around the chimney is not properly sealed. irregular installation, recommend repairs to prevent water penetration

Frank P. Macak

Page 7 of 33

6. Sky Lights Good Fair Poor N/A NI Image: Colspan="3">X		
7. Spark Arrestor Good Fair Poor N/A NI X	Observations: <i>present. stainless steel</i>	
8. Vent CapsGoodFairPoorN/ANIXAAA	Observations: <i>damaged</i>	
	<image/>	
1. Access Good Fair Poor N/A NI	Observations: <i>functional scuttle in the bedroom closet</i>	
X 2. Condition		
Good Fair Poor N/A NI	Materials: 2x8 Observations: <i>evidence of past water damage</i>	
3. Chimney Good Fair Poor N/A NI X X X X	Observations: spalling is present on the brick. water stai	ns by the roof
4. Duct Work Good Fair Poor N/A NI Markowski X A A	Observations: loose connections. bath exhaust vent duc is venting into the attic, which can cause a moisture and underneath of the roof decking in the winter, shortening structure and roof covering	ice build up on the
rank P. Macak	Page 8 of 33	Prime Inspection

Sample Street, Nearby, NY

Jane Sample

5. Electrical

oou	oou Fair	POOL	IN/A	INI
		X		

Observations: several splice connections made without J-box. spliced and taped wires. bath fan connection made outside of the housing. recommend qualified individual to make necessary connections. improper electrical installations



bath fan connection made outside of the housing

several splice connections made without J-box

6. Insulation Condition



Materials: *rolled out fiberglass* Depth: 6

Observations: irregular and insufficient installation, many areas have no insulation present. Attic requires R38-R40 insulating value. Recommend installing 2 layers of R-19 fiberglass bats in a cross pattern style



irregular and insufficient installation, many areas have no insulation present.

7. A	Attic	Plu	mbir	ng	
Good	Fair	Poor	N/A	NI	
X					

Frank P. Macak

Page 9 of 33



Jane Sample Sample Street, Nearby, NY 8. Structure Fair Poor N/A Good Observations: 2x6 ceiling joists Х 9. Ventilation Good Fair Poor N/A Observations: louvered gable vents Х 10. Vent Screens Good Fair Poor N/A Observations: bent screens Х


Foundation/Basement

Inspector shall inspect the basement walls or foundation for cracks, water penetration, effervescence, settlement an straightness. We check the girder, posts, ceiling joists, rim joists insulation, floor, sump pump, plumbing, electrical, duct work, etc. In the crawl space we are especially concerned with the moisture barrier, venting, duct work and insulation. In both areas we also look for the presence of wood destroying insect damage.

Recommendations: The foundation of the building is an essential part of the building for obvious reasons. It supports the whole structure, keeps the moisture out of the interior that is below the grade level. It is recommended that the foundation walls be properly waterproofed from the outside and if necessary from the inside. Windows wells should be properly maintained and free from debris. Because the foundation plays an important role, it is prudent to inspect the foundation walls often, as the soil condition surrounding it can change. Most foundation walls develop small cracks during the curing process of the concrete. These are small, usually hairline size contraction cracks and should be sealed with the proper sealants. If the cracks are in a "V" shape, it would indicate a structural movement or a footing settlement and should be watch more closely. If they appear to change over time there might be structural movement and a qualified contractor should be called to remedy the problem. The same applies to horizontal cracks in the foundation walls. Horizontal cracks tend to develop if there is inadequate water diversion away from the foundation walls, creating saturated soil conditions around the foundation, which in turn causes high hydrostatic pressure onto the foundation of house, eventually pushing the walls inwards, possibly cracking the wall. This condition is common in flood zone areas, as during the flood, the water table rises putting the pressure onto foundation walls. As with a "V" or step cracking that is over 3/8" wide, all horizontal cracks should be examined by a licensed and gualified contractor or a building engineer. If there is a crawl space present, it is important to have a vapor barrier installed on the dirt floor to have properly sized ventilation openings present. Most concrete floors, if properly installed, will have a vapor barrier underneath the concrete. Basement walls as well as rim joists should be insulated with a minimum of R-19 value down to 4' bellow grade.

1. Foundation Type


Materials: concrete block





previously repaired small cracks and spalling

ank P. Macak	Page 11 of 33 Prime Inspection
X	
10. Crawl space insulation	
Good Fair Poor N/A NI X I I I	
9. Sump Pump condition	
Good Fair Poor N/A NI Observations X	: some galvanized pipe sections, recommend replacement due ccumulation of corrosion on the inside of that type of pipes. Ivanized missing proper connections
8. Basement / Crawl space Plu	Imbing
7. Basement / Crawl space Ele Good Fair Y N/A X NI Observations	ectrical :: missing j-box cover. missing wire connector
Good Fair Poor N/A NI Observations	: recommend screens
6. Vent Screens	
Cood Foir Door N/A NI	: basement windows
5. Ventilation	
Good Eair Poor N/A NI	ncrete. no crawl space present
4. Floor condition	
X	



15. Stairs

Good	Fair	Poor	N/A	NI	
Х					

Observations: missing handrail. while this is very common in older homes, it is recommended that the risers be closed as to prevent the safety hazard to children. Likewise the spindles should be installed no more then 4" apart, to prevent possible injury.



missing handrail / open risers

Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, living room, dining room and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Here again we are concerned with ceilings, walls, floors, windows, lighting, electrical and the presence of a heat source.

Recommendations: Interior areas will often show small cracks on the ceilings or walls, which are normal to today's construction materials. They are most often caused by thermal contraction and expansion, moisture variation or by slight building settlement. In most cases these will not worsen. The same applies to plaster walls. If you do notice some new cracks that are larger than 1/4", then you should contact a structural engineer to determine the cause.

Frank P. Macak

Page 12 of 33



1. Ceiling Condition
Good Fair Poor N/A NI X Image: A structure Materials: drywall. plaster Observations: small cracks, normal due to age and the settlement of the structure
2. Wall Condition
Good Fair Poor N/A NI X Image: A start of the s
3. Condition
Good Fair Poor N/A NI X Image: Nide of the second s
4. Floor Condition
Good Fair Poor N/A NI X Image: A structure of the str
5. Window Condition
Good Fair Poor N/A NI X Image: Style and materials: double hung. wood/aluminum clad Observations: upper sashes painted shut
6. Light type/condition
Good Fair Poor N/A NI Observations: flush ceiling ligh. suspended light
7. Trim Condition
Good Fair Poor N/A NI X Image: A start of the start
8. Closets
Good Fair Poor N/A NI X I I I
9. Sliding Doors
Good Fair Poor N/A NI
10. Stairs & Handrail
Good Fair Poor N/A NI Good X Image: A strain of the strai

Prime Inspections



steps are pulling away from the wall

11. Electrical				
Good	Fair	Poor	N/A	N
Х				

12. Fireplace

Good	Fair	Poor	N/A	N
Х				

Location: *Living Room* Materials: *mason built* Observations: damper tested / checked. recommend professional cleaning before use



damper tested / checked

13. Smoke Detectors



Observations: present, but some did not operate, recommend replacing the battery in all of them at the same time, at least once a year

14. Door Bell Fair

Poor

N/A

NI


Good


Х

Observations: operated

```
Frank P. Macak
```

Page 14 of 33





failed sealed, moisture between panes

8. Light type/condition	
Good Fair Poor N/A NI X I	
9. Vent Condition	
Good Fair Poor N/A NI X Image: A structure of the str	
10. Electrical	
Good Fair Poor N/A X I I	
11. GFCI	
Good Fair Poor N/A NI X Dbservations: 1 GFCI by the microwave not operational by licenced electrician	l, correction needed
12. Dishw. Condition	
Good Fair Poor N/A NI X Image: A state of the state	
13. Microwave	
Good Fair Poor N/A NI X	
14. Unit Condition	
Good Fair Poor N/A NI X I Fixture type Hotpoint	
15. Cond.	
Good Fair Poor N/A NI X Image: A state of the state	
Frank P. Macak Page 16 of 33	Prime Inspections

16. Sinks
GoodFairPoorN/ANIXIII
17. Garbage Disposal
Good Fair Poor N/A NI Image: Im
18. Plumbing
Good Fair Poor N/A NI X A B A B Observations: corrosion present. missing shut off handle
19. Heating
Materials: present. hot air register

Bathrooms

Inspection of the bathroom area involves the inspection of the ceiling, wall, floor, cabinets, sinks, toilet, bidet, shower, tub, venting, electrical and the fixtures. Inspector will not turn or attempt to turn on/off any stop/shut off valves, as that by itself could cause a leak and possible water damage. In the bathroom area, we are also concerned with the possible presence of organic substances due to high moisture levels. The home inspector will identify as many issues as possible, but some problems might be undetectable if they are within the walls or under the floors. Recommendations: *Bathrooms are potential sources of the water damage in the house. Any leaks, no mater how small should be attended to immediately. Leaky faucets, shut off valves or running toilet will cause condensation on the pipes or toilet tank, which then drips onto the floor and causes water damage and potential growth of mold or mildew. If there are any fixture leaks, cold water pipes inside the walls, all the way to the entry into the house will condensate the moisture from surrounding air and will go on dripping water undetected. Any cracks in the grout or damaged caulk around the tub/shower area should be corrected as soon as possible to prevent moisture penetration into the substrate. Whenever using the shower, exhaust fan should be used to evacuate as much moisture as possible from the house to the exterior. To prevent mold/mildew growth, leave the shower curtain/door open for moisture to evaporate. Any water splashed onto the floor should be dried off ASAP.*

mold/mildew growth, leave the shower curtain/door open for moisture to evaporate. Any water splashed onto the floor should be dried off ASAP.					
1. Bathrooms					
Number of bathrooms: 1/2 bathroom. 1 full bathroom					
2. Ceiling Condition					
Good Fair Poor N/A NI X Image: A start of the s					
3. Walls Condition					
Good Fair Poor N/A NI X Image: Second					
4. Condition					
Good Fair Poor N/A NI X Image: A structure of the str					

5. Floor Condition
Good Fair Poor N/A NI X X Materials: ceramic tile Observations: grouting shows irregular workmanship
6. Window Condition
Good Fair Poor N/A NI Style and materials: double hung Observations: upper sashes painted shut
7. Light/Fan - type/condition
Good Fair Poor N/A NI X Image: A structure of the str
8. Cabinets condition
Good Fair Poor N/A NI X I I I I Materials: wood faced
9. counters
Good Fair Poor N/A NI X Image: A start of the start
10. Mirrors
Good Fair Poor N/A NI
11. Sinks
Good Fair Poor N/A NI X Image: Second Control of the counter Image: Second Control of the counter X Image: Second Control of the counter Image: Second Control of the counter
12. Toilets
Good Fair Poor N/A NI X I I I
13. Observations:
Good Fair Poor N/A NI X Image: A structure X Image: A structure X
14. Condition:
Good Fair Poor N/A NI X NI Materials: fiberglass 3 piece unit Observations: unfinished installation

Frank P. Macak

Page 18 of 33

Sample Street, Nearby, NY

unfinished installation
15. Grab Bars Good Fair Poor N/A NI X NI Observations: part of the tub
16. Plumbing
Good Fair Poor N/A NI X X Image: State of the state
17. Electrical
Good Fair Poor N/A NI X I I I
18. GFCI
Good Fair Poor N/A NI X Image: A structure Observations: GFCI, lights & fans on same circuit
19. Heating
Good Fair Poor N/A NI X Image: Second
Bedrooms
The main area of inspection, in the bedrooms, is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be inspected for damage, normal operation and the proper size for an emergency egress. Personal items in the bedroom may prevent all areas to be inspected, as the inspector will not move personal items. Recommendations: Bedroom windows serve a secondary purpose. They are very important means of egress in the case of fire, so there should never be anything stored directly in front of them or blocking easy access to possibly the only exit available. At least one of the windows should be able to open upwards at least 20 inches and be at least 24" wide or vice-versa.
1. Bedrooms

Number of Bedrooms:: 4

Frank P. Macak

Page 19 of 33

Occupied and the second state Good Fair Poor N/A NI Materials: drywall. plaster X Image: Colspan="2">Image: Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2" Y Image: Colspan="2">Materials: drywall. plaster Observations: small cracks - normal occurence	
3. Wall Condition Good Fair Poor N/A NI X NI Materials: drywall. wall paper. paneling X Observations: small holes	
4. Door Condition Good Fair Poor N/A NI X NI Observations: painted	
5. Floor Condition Good Fair Poor N/A N Materials: wall to wall carpet. hardwood X Deservations: normal wear	
6. Window Condition Good Fair Poor N/A NI X D D Servations: upper sashes painted shut	
7. Light type/condition Good Fair Poor N/A NI X Deservations: flush ceiling ligh. suspended light	
Sood Fair Poor N/A NI X V V V V	
9. Electrical Good Fair Poor N/A NI X VA NI Observations: open ground outlet in upstairs right bed	Iroom,
10. Smoke Detectors Good Fair Poor N/A NI Observations: none Good X VI VI	
11. Heating	
Materials: register present	
12. Window-Wall AC or Heat Good Fair Poor N/A NI Good Fair Poor X Observations: none	
Laundry	
The inspector will not operate the washing machine or the dryer, but will insp connections, dryer vent, cabinets and any counter tops if present.	ect the water and gas
Frank P. Macak Page 20 of 33	Prime Inspection

Recommendations: There are over 15,000 fires yearly in USA that are caused by dryers. While some are caused by the manufacturers dryer design, many are caused by the dirty dryer ducts with excessive lint built up. It is important that the dryer duct be properly installed, and be serviced at least once a year, depending on the amount of use. The best dryer vents are ridged pipe type dryer vent. They should not exceed 25' of developed length.. If using flexible plastic vent pipe, it should not be longer than 8', and should not be used with gas fired dryers. Personally I would recommend never using flexible plastic dryer vent pipe, as it tends to accumulate more lint, due to the corrugation effect, they tend to become thermally stressed and crack, they tend to crush or collapse and reduce the amount of air flow, therefore increasing the temperature and causing fires and dryer damage, and they need replacement more often.

1. Locations

Materials: ready - electric and plumbing installation is present in the basement

rank P. Macak	Page 21 of 33	Prime Inspection
Good Fair Poor N/A NI	Observations: test operated	
10. GFCI		
X		
Good Fair Poor N/A NI		
9. Electrical		
X		
8. Dryer Good Fair Poor N/A NI		
7. Washer Good Fair Poor N/A NI		
Good Fair Poor N/A NI		
6. Wash Basin		
Good Fair Poor N/A NI	Materials: none	
5. counters		
Х		
4. Cabinets Good Fair Poor N/A NI		
Good Fair Poor N/A NI	Materials: <i>concrete</i>	
3. Floor Condition		
X		
2. Light type/condit	ion	

Iane Sample	Sample Street, Nearby, NY
11. Gas Valves Good Fair Poor N/A NI X I	
12. Plumbing Good Fair Poor N/A NI X I	
	Furnace/Boiler/AC
the appliance, size in BTU's, pro- look at the distribution of the hear presence of Carbon Monoxide a The inspector will usually test the We always recommend for a new yearly basis by a qualified profest Recommendations: Heating and a When in use, whether the AC or Heating be changed every 3 months. There are recommendations for its specific mains basis by a qualified professional. Duct	burce of the heating/cooling system, approximate age and the type of oper venting, operation, ignition, and the general condition. We also ating/cooling system, duct type and condition, as well as any and the presence of other potentially harmful and explosive gases. e heating and air conditioner using the thermostat or other controls. w home buyer to have the heating or A/C systems maintained on a ssional. <i>ir conditioning systems play an important role in the quality of air in the house.</i> <i>ng cycle, filter (if applicable) should be changed every month. HEPA filters should</i> <i>e several types of electronic HVAC's filters, and the manufacturers</i> <i>tenance should be followed. Always have your HVAC system inspected on a yearly</i> <i>work tends to accumulate dust and should also be periodically cleaned. The blow</i> <i>I be used to flush the water level float valve on a weekly basis during the heating</i>
1. Model	
Brand & Year: 20	Type: Payne Plus 90 mod#: 350MAV060120. Gas furnace 02. 115,000 BTU
2. Condition	
Good Fair Poor N/A NI Materials	ent

Furnace - some rust present under the condensate fan

Frank P. Macak

Page 22 of 33

Jane Sample Sample Street, Nearby, NY 3. Gas Valves Good Fair Poor N/A NI Observations: functional. located to the right 4' up Х furnace shutoff located to the right 4' up 4. Thermostats Poor N/A Good Fair NI Х 5. Venting Fair Poor Good N/A NI Observations: tested for proper draft Х 6. Filter Location/Condition Poor Good Fair N/A NI Observations: inside the heater. recommend replacing once a month during Х heating/cooling season 7. Air Supply N/A Good Fair NI Pool Observations: air draws from garage area Х 8. Ducts / Registers Good Fair Poor N/A NI Х 9. Type / Location Poor Good Fair N/A NI Observations: A/C not present Х

10. Condition

Good	Fair	Poor	N/A	NI
			Х	

Frank P. Macak

Page 23 of 33

Prime Inspections

Frank P. Macak

Prime Inspections




Furnace - some rust present under the condensate fan

Water Heater

The inspection of the water heater is important because it is a possible source of dangerous CO (Carbon Monoxide). We look for proper venting, correct T&P relief valve and proper pipe extension. We also test for gas leaks with gas water heaters.


Recommendations: Hot water temperature above 120 F poses a serious safety hazard, especially to children, elderly and people with poor circulation. It takes only 5 seconds of water temperature set at 140 F to cause a third degree burn and 30 seconds at 130 F. Every year 112,000 people are treated for scald burns of which approximately 50% are children according to Safe Kids Coalition. To prevent explosions, hot water heaters are protected by a T&P relief valve, designed to relieve pressure in the case of overheating. Manufacturers recommend replacing the T&P valve every 3 years. The T&P valve should be tested vearly for proper operation by lifting the tab. allowing it to purge small amount of water and letting go of the tab. Spring loaded valve should shut down by itself. Should the valve not release water or not shut down properly, it would need to be replaced. T&P valve should never be capped!!! Work should be performed by a licensed professional. Click on the link bellow to see the potential danger:

http://www.youtube.com/watch?v=pu3FwgIHsQA - fast forward to 6:50






improper clearance to combustible materials



Observations: located on the right side of the water heater



FYI - gas shutoff location - and missing T&P valve extension




Ticensed professional and dealt with in a timely manner. However, common sense should always be used in the daily use of electrical appliances and outlets. Never overload the circuits by the use of multiple heavy wattage appliances on the same circuit. Do not use multiple appliances on the single extension cord. Only use the extension cord when absolutely

Frank P. Macak

Page 25 of 33



Sample Street, Nearby, NY



Page 26 of 33




multi wires to one breaker

DWV (Drain / Waste / Vent)

The waste lines inspection consist of a visual inspection of the DWV (drain, waste, vent) pipe type and their condition, proper pitch, and presence of any leaks.

Recommendations DWV pipes should never be used to hang items from, or as a storage shelf. Many people often use it as such, especially when it runs along the walls of the basement at a convenient hight. Because DWV carries waste water, any leaks should be corrected immediately to prevent any bacterial spread and dangerous mold growth such as stachybotris also known as black mold.

1. Waste condition



Materials: PVC into Cast iron Observations: venting through the roof

Water Supply

The inspection involves determining the type of water supply, (well or city), type of supply pipe present, the condition of the water meter if present, jumper presence and the physical location of the meter.

Recommendations: The supply pipe that the water meter is mounted on carries all of the water that's being used in the house. Because that water comes from underground piping and is colder than the surrounding air, the surface of the pipe tends to condensate and drip water onto the floor. It is important to insulate the supply pipe at the entry into the house. If you notice, especially in the summer on humid days, that there is condensation on the pipe farther up the line, then additional pipe insulation should be added, for the full distance of condensation occurence. If the condensation is throughout the basement piping, all faucet, toilets and water outlets should be checked for active leaks. It might also be necessary to run dehumidifier in the basement area.

1. Water source

Materials: municipal water

2. condition



Pipe type: 3/4" copper Location: basement right Observations: no bond jumper present

Page 27 of 33




water main shutoff

Gas / Oil Supply

Here we determine the type and source of fuel, location of the oil tank if present, location of the gas meter if present and check for any fuel leaks.

Recommendations: Areas around the gas meter and gas shutoff valve or oil tank and oil shutoff valve need to be kept accessible at all times. Any detected or apparent gas leaks should be immediately reported to your gas utility company. Any oil spills during filter changes should be promptly cleaned up. During the yearly maintenance of the furnace/boiler, fuel storage tanks should also be inspected for leaks and corrosion.

1. Main Gas Valve Condition




Location: *north side. exterior of structure* Observations: *natural gas*



natural gas - main shutoff

2. Condition



Frank P. Macak

Page 28 of 33

3. Fuel & CO leaks

Condition: *Tested - none present*


. Locations tested include: main gas valve and piping. connections to water heater. any visible threaded or union connection of the gas pipe. CO presence tested in the . basement, utility area

Garage

The garage is part of a general home inspection, and we inspect the same elements as we do in the main house structure. In the case of an attached garage, we are especially concerned about the fire ratings of the house entrance door and the condition of the firewalls, as well as any fuel burning appliance installation.

Recommendations: The garage should never be used to store any flammable materials. An attached garage is designed with a fire rated ceiling, walls and separation doors. There should be a minimum of a 4" step, up to an adjacent living area according to modern building codes. This is to prevent any flammable fumes from drifting into the living area.. Any combustion operated devices such as furnace/boiler, gas hot water heater etc,. must be elevated 24" above the surface of the floor. Self closing doors should not be left open by any means of obstruction. Vehicles should not be left running in the garage as they produce high levels of carbon monoxide which is deadly. Turn the ignition off as soon as you pull in or drive out immediately after starting the vehicle. Do not let it idle and warm up in the garage. Proper lubrication of the garage doors will assure smooth and safe operation. Any worn parts should be replaced, as not to cause damage to other components. Safety stop and eye sensors on the opener operated garage doors are adjustable and should be kept in proper working order. Regular checks and testing is necessary.

1. Roof Condition



Materials: 1 sloped roof. 1 under unit Materials: rolled roofing Observations: weathered, walked on, remaining useful life: 2-4 years left with proper maintenance

2. Rafters & Ceiling



Observations: cracked rafters, probably due to a snow weight on the roof. Recommend repairs by a qualified contractor.



cracked rafters



Page 29 of 33

Jane Sample Sample Street, Nearby, NY 3. Walls Good Fair Poor N/A NI Observations: missing drywall tape. no firewalls present. missing fire Х resistant drywall, constitutes a safety hazard missing drywall in areas 4. Flooring Condition Good Fair Poor N/A NI Materials: blacktop Х 5. Window Condition Fair Poor N/A Good NI Х 6. Garage Door Condition Fair Poor Good N/A NI Materials: sectional wooden overhead door with glass Х 7. Garage Opener Status Good Fair Poor N/A NI Х 8. Garage Door's Reverse Status Good Fair Poor N/A NI Х 9. Electrical Poor N/A Good Fair NI Х 10. Exterior Door Good Fair Poor N/A NI Х

Frank P. Macak

Page 30 of 33

Prime Inspections

Jane Sample	Sample Street, Nearby, NY
11. Fire Door Good Fair Poor N/A NI Observations: house entry door present - fire X Discriptions: house entry door present - fire	rated
12. Foundation Good Fair Poor N/A NI X NI Observations: concrete block, part of the house	se structure,
13. Siding Good Fair Poor N/A NI X NI Observations: same as the house	
Approximate Cost Estimates	
Minor repairs required during the first year of occupancy:	

- exterior foundation cracks......\$ 150.00 \$250.00 - caulking and siding repair......\$ 100.00 - \$250.00

- other miscellaneous repairs.....\$ 150.00 \$200.00

Total approximate cost\$ 950.00 - \$ 1800.00

Please remember that this is just a best guess of the costs of repairs by an inspector. Actual cost estimates need to be obtained from licensed professionals.

Larger necessary repairs such as electrical panel and other electrical issues if any, roof replacements or any damages sustained by leaks, systems that are currently not operational or are at the end of their useful life cycle and are noted in the inspection report, costs of possible ACM removals are not included in the costs above. Those cost estimates should be obtained from qualified and licensed professionals.

All cost estimates should be obtained prior to closing.

Page 31 of 33

Conclusion

I am glad to report to you, that the inspected property appears to be in a good condition. The property appears to have been well maintained with many new improvements present, that were done in good workmanship.

Like with every other property, there are some small deficiencies and some safety hazards discovered. Safety issues are pointed out in the Summary section for an easy overview, and they should be addressed before the closing of the property, as some of these issues may be the responsibility of the seller.

WDO - Inspection for the presence of WDO involves visual inspection of readily accessible components of the structure that are susceptible to WDI attacks such as areas near the ground, crawl space, basement and attic areas. Any issues discovered would be incorporated into the report as well as they would show up in the summary page at the end of the report. I found no evidence of the presence of termites, shelter tubes, frass or WDI insects body parts. This is not a waranty or a guaranty, as parts of the basement are finished and were not accessible for an inspection.

Well test report was incorporated into water supply section.

Septic dye test was performed according to the standard protocol. Dye was introduced into the system through the 2nd bathroom toilet. Outflow was verified. Single outflow/single septic system present. Septic system was loaded with a flow of 4gal per minute for 60 continuous minutes - for a total load of 240 gallons. No evidence of dye or/and surfacing effluent was detected. Septic system has passed the test.

Radon and water quality test results will be forwarded to you as soon as they are available.

Please understand that this inspection is a snapshot in time, and the conditions of the home and systems can and do change. Any system or part of the system can fail. This report is not a guarantee or warranty of the structure or any system therein. I have tried to make this report as clear as possible and I hope that the findings and the recommendations were helpful to you in understanding your new property. We always recommend to do a final walk through prior to closing.

If you were satisfied with the inspection and report, I would appreciate if you let your realtor, mortgage broker and your friends who are planning on buying or selling a house, know about your satisfaction with us and recommend us to them for the future transactions.

We recommend that you retain the report for future reference and important information about the location of gas/electric/water shutoffs, and other helpful maintenance information regarding your new property. To find out more info on environmental issues such as radon, asbestos, mold, water, safety, children's health etc., you can go to :

(clickable link) http://www.prime-inspect.com/index.php?p=1_4_Links

Should you need any further inspections or testing such as mold sampling, water quality testing, radon testing, septic system dye test etc. please feel free to contact me. I have included extra photos at the end of the report to give you a better sense of the property. If you have any questions regarding the deficiencies discovered, please feel free to call me anytime. Best wishes. With regards,

Frank

Note: This report is a property of Prime Inspections and the Client that has purchased the report, and it shall not be relied upon or be used by any means, by any other party in any other transaction without specific permission from Prime Inspections and the report's purchaser.

Page 32 of 33

Report Summary

The summary below consists of potentially significant findings. These findings identify safety hazards, a deficiency requiring a major expense to correct, or items I would like to draw extra attention to. Please review all of the pages of the report, as the summary alone, does not explain all of the findings. We recommend that all repairs should be done by a licensed professional and all estimates be obtained prior to closing on the property.

Grounds		
Page 2 Item: 4	Stairs & Handrail	loose step and missing spindle pose a safety and trip hazard. The missing spindle creates a condition where a child could get trapped and seriously injured. Immediate correction is needed.
Attic		
Page 9 Item: 5	Electrical	improper electrical installations
Kitchen		
Page 16 Item: 11	GFCI	1 GFCI by the microwave not operational, correction needed by licenced electrician
Bedrooms		
Page 20 Item: 9	Electrical	open ground outlet in upstairs right bedroom,
Water Heater		
Page 24 Item: 2	TPRV	T&P relief valve is missing extension pipe.
Page 25 Item: 4	Venting	Vent pipe touching combustible materials - fire hazard
Electrical		
Page 27 Item: 4	Breakers	multi wires to one breaker
Garage	1	
Page 30 Item: 3	Walls	missing fire resistant drywall, constitutes a safety hazard